

## **Release Notes masterCONFIGURATOR V2.32.0.73**

### Software changes:

- ☐ Output channel grouping for LED Driver with firmware higher than 1.5 moved to companionSUITE

### Solved software-bugs:

- ☐ Control gear wizard is visible again after being greyed out

## **Release Notes masterCONFIGURATOR V2.31.0.72**

### Software changes:

- ☐ New: Intelligent voltage guard + ( IVG+ )
- ☐ New: Integrated DALI power supply
- ☐ Renaming of "Fade2Zero" to "Soft stop"
- ☐ Renaming of the buttons in the main and group view to "save" and "test"
- ☐ ETM: Change of upper input limit for individual NTC sensor settings (BETA and R25)
- ☐ chronoSTEP 2: Added parameter "Power on level"
- ☐ Update of the devicelist

### Solved software-bugs:

- ☐ LMI device (DC-string): Adaption of readdressing sequence
- ☐ ready2mains Programmer: Change of the stats when starting the addressing.

## Release Note masterCONFIGURATOR V2.30.0.70

### Software changes:

- ☐ Detect and clear of double addressing
- ☐ New features implemented (ITG-Offset, CLO2, ETM, inputDIM)
- ☐ DT8: change of physical MIN/MAX border now possible
- ☐ basicDIM DGC: improved
- ☐ New products implemented

### Solved software-bugs:

- ☐ basicDIM DGC: Output configuration does not work solved
- ☐ LMI device (DC-string): Adaption of readdressing sequence

## Release Note masterCONFIGURATOR V2.28.0.66

### Software changes:

- ☐ Update of masterCONFIGURATOR and DALI Monitor toolbar
- ☐ corridorFUNCTION: add possibility to set hold time
- ☐ factory reset extended with the possibility to reset the current to default value
- ☐ Search speed optimized
- ☐ New products implemented
- ☐ DALI BusServer and Monitor improved

### Solved software-bugs:

- ☐ basicDIM DGC: various bugs solved
- ☐ MSensor: various bugs solved
- ☐ DALI XC: various bugs solved
- ☐ DT8 bugs solved
- ☐ SW crash when using PCA with SMART Sensor solved
- ☐ DALI Monitor: Filter function bugs solved
- ☐ Additional smaller bugs solved

## Release Note masterCONFIGURATOR V2.26.0.54

### Software changes:

- ☐ Rapid commissioning wizard implemented in main view
- ☐ New Main view implemented with additional commissioning possibility's
- ☐ New Group view implemented with additional commissioning possibility's
- ☐ Easy Grouping implemented (add remove groups with keys in device window)
- ☐ Dali Monitor – LogFile concept implemented
- ☐ New Tridonic devices implemented
- ☐ DT4 - implemented

### Solved software-bugs:

- ☐ basicDIM DGC: various bugs solved
- ☐ MSensor: various bugs solved
- ☐ DALI XC: various bugs solved
- ☐ SW crash after pressing r2m Programmer related buttons solved
- ☐ SW crash caused by new DaliBusServer solved
- ☐ DT8: missing extended fade time implemented
- ☐ I-Select min and max values shown wrong solved
- ☐ Pressing read button now read all data from device
- ☐ German texts in English version removed
- ☐ Additional smaller bugs solved

## Release Note masterCONFIGURATOR V2.24.1.35

### Software changes:

- ☐ Buttons without functions removed
- ☐ It's now possible to send in command administrator commands to only unaddressed devices
- ☐ Implementation of DALI usage graph in Dali Monitor
- ☐ Implementation of Google analytics

### Solved software-bugs:

- ☐ MSensor: if motion detection is deactivated the "run on time" was faulty set to infinite
- ☐ Software crash after deleting empty groups in the tree view fixed
- ☐ Problem within displaying wrong chronoSTEP values fixed
- ☐ COT-File Timing improved

## Release Note masterCONFIGURATOR V2.24.0.9

### Software changes:

- ☐ Implementation of ready2mains Programmer for use as a DALI USB
- ☐ Better presentation of "Locate" and "Identify" function
- ☐ "Control gear wizard" Expand the corridorFUNCTION with DALI V2 commands
- ☐ Multiple instances of masterCONFIGURATOR with different DALI USB on one PC now possible

### Solved software-bugs:

- ☐ Software crash if DALI USB is removed solved
- ☐ Addressing: clear the tree before searching devices
- ☐ "Tridonic specific configuration": no data update of Tab "Device operating mode" fixed
- ☐ "Command Administrator": Error in command sequence timing fixed
- ☐ Tuneable White and LCA 100W:  
DC-Level input field mistakenly greyed out is now working correct
- ☐ masterCONFIGURATOR stops working after selecting the "online device" icon
- ☐ TreeView: "Search devices": now also check the grouping
- ☐ Command Administrator: Software crash after deleting commands out of an existing file fixed
- ☐ MSensor // MSensor 02 // MSensor 5DPI: Name for V1.5 and V1.7 corrected
- ☐ DALI XC and DALI MC: Filename filled out with Chinese characters fixed

## Release Note masterCONFIGURATOR V2.22.0.1596

### Software changes:

- ☐ Status information for multi device type's now supported.
- ☐ Lamp Type" replaced with "Light source Type" according to DALI V2
- ☐ Emergency, after mains return, emergency mode is retained for: xx min can now be programmed in 0,5 min steps

### Solved software-bugs:

- ☐ DT6 linear / logarithmic handling was wrong. After changing the tab the programmed value was wrong
- ☐ ITM: Actuator Status 2 will be refreshed by changing the tab in the past version it was necessary to readdress the device.
- ☐ chronostep2 reduction time was limited to 10 hours now its corrected to 12 hours.

### Known Bug:

- ☐ Bug blank window. By switching from one device to another sometimes the maCO window is blank. To solve this bug resize the window of maCO.
- ☐ If you are using COT Files then please use Version V2.18 because in the newer version the timings programmed in the COT Files are not accurate enough.

## Release Note masterCONFIGURATOR V2.20.0.1565

### Software changes:

- ☐ Add "up/down" functionality to command sequence
- ☐ New file "Devicelist.txt" for article-number and device name available

### Solved software-bugs:

- ☐ basicDIM DGC drop down text mismatch corrected
- ☐ DALI XC bug fixes

### Known Bug:

- ☐ Bug blank window. By switching from one device to another sometimes the maCO window is blank. To solve this bug resize the window of maCO.

## Release Note masterCONFIGURATOR V2.18.0.1443

### Software changes:

- ☐ r2m Gateway implemented

### Solved software-bugs:

- ☐ Fast fade time cannot be set to 0! Correct values implemented.
- ☐ basicDIM DGC drop down text mismatch corrected
- ☐ ITM -> wrong parameter description corrected
- ☐ DALI RM/S - Identifikation with Firmware V1.6

## Release Note masterCONFIGURATOR V2.16.0.1407

Software changes:

- ☐ DC-string
- ☐ Hyperion outdoor
- ☐ chronoSTEP 2
- ☐ Current consumption
- ☐ I-Select Protocol
- ☐ DALI BusServer V2.7.5, prepared for ready2mains

Solved software-bugs:

- ☐ Firmware updates
  - Additional window will now pop up and warn the user. Additional information are in the documentation (9.4 Firmware update).

## Known Bugs:

- ❑ Bug blank window. By switching from one device to another sometimes the maCO window is blank. To solve this bug resize the window of maCO.

## Release Note masterCONFIGURATOR V2.14.0.1363

### Software changes:

- ❑ DALI V2 (Hyperion LED device) implemented
- ❑ DALIBusServer V2.6.4: Supporting the new DALI V2 commands in the DALI-Monitor.

### Solved software-bugs:

- ❑ basicDIM DGC:
  - Set scenes: relay output - option MASK correction.
- ❑ DALI XC:
  - Change action edge from macro "user-defined command sequence" to rising edge. Now long press (switch) is supported.

## Known Bugs:

- ❑ Bug with Firmware updates please see additional information in documentation (9.4 Firmware update).
- ❑ Bug blank window. By switching from one device to another sometimes the maCO window is blank. To solve this bug resize the window of maCO.

## Release Note masterCONFIGURATOR V2.12.0.1316

### Software changes:

- ❑ basicDIM DGC implemented.
- ❑ MSensor 5DPI 14 implemented.

### Solved software-bugs:

- ❑ DALI XC
  - Different user interface optimisations.
  - In combination with DALI XC V1.3 now also ED Commands are supported ("Macro: user-defined command sequence")
- ❑ I-Select:
  - Values are now read out correctly.

## Known Bugs:

- ❑ Bug with Firmware updates please see additional information in documentation (9.4 Firmware update).

## Release Note masterCONFIGURATOR V2.10.1.1170

Software-changes:

-

Solved software-bugs:

- ☐ Problem with MSensor is solved

## Release Note masterCONFIGURATOR V2.10.0.1155

Software-changes:

Solved software-bugs:

- ☐ Problems with LED-converter i-select and ITM solved

## Release Note masterCONFIGURATOR V2.8.2.1048

Software-changes:

New Software Features:

- ☐ New LCAI ECO led control gear supported
- ☐ ChronoStep (DT6)
- ☐ I-Select
- ☐ CLO and OTL (DT6)
- ☐ New devices added

Solved software-bugs:

- ☐ Streetlight Chronostep
- ☐ MSensor absence on groups
- ☐ Actuator-status 2
- ☐ Streetlight optical balancing limited
- ☐ Performance increasing of reading data's
- ☐ Problem with window switching to background
- ☐ Colours in corridorFUNCTION menu
- ☐ System extension was not possible
- ☐ Several other bug fixes

A detailed description of the software-changes and the new software-features can be found in the operation manual, available on the website of Tridonic ([www.tridonic.com](http://www.tridonic.com)).



## Release Note masterCONFIGURATOR V2.6.0.954 (30.01.2012)

Software-changes:

New Software Features:

- ☐ New touchPanel02 now supported
- ☐ Design / tuneable white to touchPanel02
- ☐ New devices added

Solved software-bugs:

- ☐ Firmware-update window
- ☐ Automatic refresh in Detail view
- ☐ Info window "Read out Data"
- ☐ TERMINATE at the end of commands at MSensor 02
- ☐ Device search => new commands
- ☐ MSensor version wrong window after new initialisations
- ☐ firmware update for daliTouch02
- ☐ design change emergency
- ☐ Tridonic-specific configuration => corridorFUNCTION => store false mode
- ☐ HID Parameter wrong
- ☐ DALI Touch panel improvements
- ☐ DT1: Query Features > all bits
- ☐ A lot of other parameters, false values and window specific parameters

A detailed description of the software-changes and the new software-features can be found in the operation manual, available on the website of Tridonic ([www.tridonic.com](http://www.tridonic.com)).

## Release Note masterCONFIGURATOR V2.4.0.848 (13.8.12)

Software-changes:

New Software Features:

- ☐ Streetlight converters LCAI 2x050/0500 K013 one4all; LCAI 2x038/0500 K013 one4all supported. (Optical Balancing)

Solved software-bugs:

- ☐ SMART tabs not automatically updated after change of Sensor or Plug.
- ☐ SMART Sensor presence detection settings were shown wrong after changing the settings to "only OFF"
- ☐ Status information for "Dimming on DC" was always "Yes".
- ☐ In combination with older PCA like the PCA 1x18W T8 Excel one4all (22085245) the software can shut down.
- ☐ In combination with older colour drivers the software can shut down.
- ☐ Serial number is shown wrong.
- ☐ In combination with older PCA like the PCA 1x18W T8 Excel one4all (22085245) the software can shut down.

Known issues:

- ☐ The masterCONFIGURATOR is not compatible with the software Talexx Sequencer. The
- ☐ Talexx Sequencer has to be uninstalled before installing the masterCONFIGURATOR.

A detailed description of the software-changes and the new software-features can be found in the operation manual, available on the website of Tridonic ([www.tridonic.com](http://www.tridonic.com)).

## Release Note masterCONFIGURATOR V2.2.0.792 (1.6.12)

Software-changes:

New Software Features:

Solved software-bugs:

- ☐ Changing to advanced settings in the "DALI-touch PANEL" configuration window causes the program to shut down.
- ☐ While a "new initialisation" the "DALI-MC" is not addressed when the option "control unit" is active, the option "Addressing without visible response" is inactive and a "DALI-MSensor" is connected to the DALI-Bus.
- ☐ Within device type 8 it was not able to set the light level on "MASK" when the colour temperature is changed.
- ☐ Writing a .cot file to a "DALI-MC" causes the DALI-circuit to stop answering.
- ☐ Saving the settings to the "motion detector" of the "DALI-MSensor" was not working and the DALI-Bus was not answering for about 15 minutes.
- ☐ Older LED colour devices caused the program to shut down.

Known issues:

- ☐ In combination with older PCA like the PCA 1x18W T8 Excel one4all (22085245) the software can shut down. Alternatively these ballasts can be configured with older versions of the masterCONFIGURATOR. The bug will be solved in the release 2.4.
- ☐ The masterCONFIGURATOR is not compatible with the software Talexx Sequencer. The Talexx Sequencer has to be uninstalled before installing the masterCONFIGURATOR.

A detailed description of the software-changes and the new software-features can be found in the operation manual, available on the website of Tridonic ([www.tridonic.com](http://www.tridonic.com)).

## Release Note masterCONFIGURATOR V2.2.0.785 (2.5.12)

### Software-changes:

- ☐ Quick test instead of control gear configuration for all device types
- ☐ DALI devices: new symbols for DALI control gear have been added
- ☐ New interface for DALI MSensor 1.5
- ☐ Device type 0: control gear for fluorescent lamps: new interface
- ☐ Device type 6: control gear for LED: new interface
- ☐ Adjusted interface for all device types
- ☐ Addressing Filter window was renamed to Options
- ☐ pcaCONFIGURATOR was renamed to control gear wizard
- ☐ The Options pop-up window: eD addressing has been limited to 64 eD addresses

### New Software Features:

- ☐ Compatibility to DALI Standard V1.0
- ☐ DALI MSensor 02 has been integrated into the masterCONFIGURATOR
- ☐ DALI MSensor 02: reference devices can be added and removed
- ☐ DALI MSensor (versions 1.5 and 1.7): reference devices can be added and removed
- ☐ Tridonic-specific configuration pop-up windows (device operating mode, features, compatibility settings, date of commissioning, status, functional overview)
- ☐ SMART sensors and SMART plugs (device type 0) can be configured
- ☐ Device type 8 has been integrated: control gear for colour converter (Colour temperature along the planckian curve, xy-coordinates)
- ☐ Device type 255 has been integrated: multi-device type (device type 6 & 8)
- ☐ DALI BusServer: new version is installed
- ☐ Selecting an interface: only the DALI SCI2

### Solved software-bugs:

- ☐ Enable/disable bug of MSensor – Light sensor window in English version fixed. Wrong naming in the MSensor light sensor window.

A detailed description of the software-changes and the new software-features can be found in the operation manual, available on the website of Tridonic ([www.tridonic.com](http://www.tridonic.com)).

## Release Note masterCONFIGURATOR V2.00 (7.4.2011)

### Software-changes:

- ☐ .. Functionality of configTOOL fully implemented in the masterCONFIGURATOR (configTOOL will not be continued or further supported)
- ☐ .. Changes in the appearance of the menu-bar and toolbar
- ☐ .. Changes in the window appearance
- ☐ .. Changes of adjustment range of the parameter power-on level according to the new DALI standard
- ☐ .. Extension of the command list in the command administrator according to the new DALI standard
- ☐ .. Corrections in the German and English translation

### New Software Features:

- ☐ .. DALI device types self-contained emergency devices (DT1), HID-devices (DT2), LV-transformers (DT3), phase control dimmer (DT4) and LED-Converter (DT6) added (functions like in the configTOOL)
- ☐ .. Implementation of an installation wizard (function like in the configTOOL)
- ☐ .. Extension of group and broadcast configuration (function like in the configTOOL)
- ☐ .. Implementation of the pcaCONFIGURATOR (function like in the configTOOL)
- ☐ .. DALI-MC eDALI Commands in Macro 8 (user definend CoT) added

### Known software-bugs:

- ☐ .. Wrong naming in the MSensor light sensor window  
With the MSensor parameter "Daylight-linked closed-loop control" the light sensor can be enabled or disabled. In the English version of the masterCONFIGURATOR V2.0.0 the naming of the parameter "Daylight-linked closed-loop control" is inverted.
  - Choice box parameter "Daylight-linked closed-loop control"=>enabled will disable the light sensor
  - Choice box parameter "Daylight-linked closed-loop control"=>disabled will enable the light sensor.Work-around: The correct status of the light sensor is indicated in the status field "status" in the same window. With this status can be check if the light sensor is active or inactive.

### Solved software-bugs:

- ☐ .. Malfunction in the localise function

A detailed description of the software-changes and the new software-features can be found in the operation manual, available on the website of Tridonic ([www.tridonic.com](http://www.tridonic.com)).